GENERATOR WINDING INSPECTION												
CUSTOMER INFORMATION												
Customer'	's Name		PPSI Use	ed	Contact	Eric	Plebuch	Phone #	((541) 501-2	696	
Location		EUG YA	RD	Unit #	UE0	1190	Work order	2938	3194	DATE	4/4/2019	
				GENEF	ATOR NA	ME PLATE	INFORMATI	ON				
Engine Se	erial #:	E5	A01189	Ar/ Spec #					Hours	1	000	
Generator	Serial #	F3	A03641	Ar/ Spec #					Volts		480	
Rated Amperage @ .8pf:				KW:		100		Standby		or Prime?		
Hertz:			<u></u>	KVA:		RPM	M		Single or Three Phase 3			
Heaters? Vear of Manufacture: Date of L									Date of las	t inspection	1 -	
CATERPILLAR GENERATOR INSULATION TEST SPECIFICATIONS												
METER: SPECS:	 METER: Use 500 volt dc for generators 600 vac or less Disconnect grounds, leads, fuses, meters and controls. Lockout/ tagout of system is required. Discharge the capacitance of the windings, disconnect " TO" from ground. Red lead of meter to ground ("+"). Connect black lead to "TO" ("-") SPECS: New generators should be 30 megohms or greater Minimum resistance should be at least 1 megohm. Inspections should be performed as close to the same temperature and humidity conditions as the previous test. Resistance should rise between 30 second and 60 second readings. Loss of 50% or greater resistance from previous testing indicates moisture in windings. Dry out windings and retest. Windings should be 5*C (8*F) above ambient temperature to keep out moisture. 											
CLEAN: Wipe with a dry lint free cloth on low voltage systems only. Solvents may be used as per manufacturer recommendations. Caterpillar recommends hydrosolve solution between 5% to 100% strength ***Generators should be cleaned, dipped and baked when windings fall below manufacturers specifications***												
			30second	60se	cona	Ambi	ent temp		Com	ments:		
MAIN STATOR - A			>500 M	>50	>500 M		51		P	Pass		
MAIN STATOR - B			>500 M	>500 M			51		Pass			
MAIN STA	ATOR -	C	>500 M	>50	<u>ю м</u>		51		P	ass		
						-						
MAIN RO	TOR											
			1			1						
EXCITER	STATOR											
			1			1						
EXCITER	ROTOR					I						
	TOD		1			1						
PMGSTA	TOR											
DEAL	ATOP	OTING			040							
REGUL	ATOR TE	STING		NOL					FULL LOA	D		
			VOLTAGE	AN	IPS	OHMS (1)		VOLTAGE		A	MPS	
F1 I0 F2												
20 TO 22						_						
20 TO 24						4						
24 TO 30	(SE ONL)	()				4						
26 TO 28	(PM ONL)	Y)										
26 10 30	(PM ONL)	Y)										
28 10 30	(PM ONL)	Y)										
COMMENTS: NOTE: OHMS(1) FOR FIELD IS MEASURED WITH ENGINE STOPPED												
The unit passed after drying the main windings												
CUSTOMER	SIGNATUR	E			TECHNICIAN	SIGNATURE						
							Ν	like Curre	en			
PETERSON POWER SYSTEMS 800-621-9087												
l												

Γ